



Assembly Instruction for Fiber Optic Series FOH Fischer Connectors



Table des matières

1	Introduction	3
2	Document history	3
3	Definitions and Acronyms	3
4	FOH Plugs & Receptacles with Potting Set.....	4
5	FOH R01, R03 & R13 Receptacles with Wire Set.....	9
6	Terminus assembly	12
7	Polishing	14
8	Appendix	22

1 Introduction

This document covers :

- The application of Fischer FiberOptic Series electrical contacts and optical termini to electrical and fiber optic cables (singlemode and multimode fibers)
- The assembly of fiber optic cable with a cladding size of 125 µm and having the cable structure described in Fischer FiberOptic Series Cable Specifications
- The assembly of Fischer FiberOptic Series electrical contacts and optical termini and Rear Accessory sets (Wire, Cable Clamp and Potting sets) to Fischer FiberOptic Series Hybrid (referred as FOH in the present document)

Please read these instructions thoroughly before starting assembly.

2 Document history


Date	Revision #	Author	Controller	Modification description
15.03.2017	6.0	JGY	SRH/CMI	New Document
06.04.2017	7.0	JGY	SRH/CMI	Adding instruction for electrical contact assembly §6
06.07.2018	7.1	SKE	JGY	Correct references of component list in §4
28.02.2019	7.2	SKE	JGY	Rear of Sleeve Holder changed from black to red

3 Definitions and Acronyms

Text	Definition / Acronym
FO	Fischer FiberOptic
FO H	Fischer FiberOptic Series Hybrid
IEC	International Electrotechnical Commission

4 FOH Plugs & Receptacles with Potting Set

Assembly steps



Components list :

- A – Sleeve Holder
- B – Connector Body
- C – Insulator
- D – Optical termin
- E – Electrical termin
- F – Support Washer
- G – O-ring Seal
- H – Potting Set Body
- I – Crimping Sleeve
- J – Rear Nut
- K – Shrink Tube
- L – Bend Relief

Note : the pictures shown in this section represent a P01 Plug.


The following assembly steps are valid for P01 plug, as well as R01, R03, R13 and R50 receptacles, except the final step (sleeve holder assembly).

Assembly steps

Picture	Process	Tools
	<p>Slide over the cable :</p> <ul style="list-style-type: none"> - the Bend Relief "L" - the Shrink Tube "K" - Crimping sleeve "I" - the Rear Nut "J" - the Potting Set Body "P" - the O-Ring Seal "G" 	
<p>A: 70 [mm] B: 7 [mm] C: 54 [mm] D: 0 [mm] E: 42 [mm] F: 5 [mm]</p>	<p>Strip the cable to the dimensions as given on the picture.</p>	<p>Ruler, aramid shears, jacket stripper, and strip tool.</p>


Terminus assembly : see section 6

Polishing: see section 7




Insert all the Termini "D" & "E" into the Insulator "C".


When you insert the Terminus "D", be careful to turn it during the insertion to not "bend" the contact O-ring.








Pin Layout front view.





Place the Support Washer "F" around the Termini "D" & "E".



Push the contact bloc (Termini "D" & "E" + Insulator "C") with the Support Washer "F" until it clips.


	<p>Position the O-Ring Seal "G" on the Potting Set Body "H" then slide the Potting Set Body "H" into the Connector Body "B".</p> <p>Be careful to the orientation of the back body.</p>	
	<p>Screw by hand the Rear Nut "J" on the Connector Body "B".</p>	
	<p>Screw the Rear Nut "J".</p> <p>Recommended torque : 5.0 Nm</p>	<p>Torque wrench [5Nm] Size 16 Counter piece: receptacle FO2/4</p>
	<p>Crimp the ground contact onto the Potting Set Body "H" using the Crimping Sleeve "I".</p>	<p>Find tools drawing in appendixes.</p>
	<p>Slide the Shrink Tube "K" until the end of the shrink tube abuts the Potting Set Body "H" as shown on the left picture and heat it.</p>	<p>Heat gun</p> <p>Shrink tube operating temperature range : -55°C to 110°C..</p>



Slowly inject the epoxy inside the Potting Set Body "G" using the filling hole located at the bottom of the Potting Set Body "G".


Note : the second hole, smaller and located above the filling hole, is an overfilling hole. Stop injecting epoxy when epoxy starts to flow from this overfilling hole.

Resin Epoxy RS 851-044 Black




Remove any excess epoxy from the assembly (if any), apply tape on both filling and overfilling holes and place the assembly onto the curing oven block.

Curing time : 12 hours @ approx. 23°C.



Apply epoxy on the Shrink Tube "K" and slide the Bend Relief "L" until the end of the Bend Relief "L" abuts the Rear Nut "J".

Epoxy: RT-355 Resintech




Insert Sleeve Holder "A" in Connector Body "B" with red side inside connector.

Note : there is no Sleeve Holder for R01, R03, R13 and R50 receptacles. Thus, this final assembly step is valid only for P01 plug.







5 FOH R01, R03 & R13 Receptacles with Wire Set







Assembly steps





Components list :

- A – Connector Body
- B – Insulator
- C – Termini (Electric & optic)
- D – Support Washer
- E – Crimp Sleeve
- F – Shrink Tube
- G – O-Ring Seal
- H – Wire Set Body
- I – Wire Set Nut
- J – Connector Panel Seal
- K – Connector Nut

Picture	Process	Tools
	<p>Slide over the cable :</p> <ul style="list-style-type: none"> - the Wire Set Nut "I" - the Wire Set Body "H" - The O-Ring Seal "G" - the Shrink Tube "F" - the Crimp Sleeve "E" 	
	<p>Strip the cable to the dimensions as given on the picture.</p>	<p>Ruler, aramid shears, jacket stripper, and strip tool</p>
Terminus assembly : see section 6		
	<p>Uniformly distribute the cable strength members around the back of the Terminus "B".</p>	
	<p>Slide the Crimp Sleeve "E" over the cable strength members until the end of the Crimp Sleeve abuts the Terminus "B".</p>	<p>Find tools drawing in appendixes.</p>


Picture	Process	Tools
	<p>Slide the Shrink Tube "F" over the Crimping Sleeve "E" and heat it.</p>	<p>Heat gun Shrink tube operating temperature range : -55°C to 110°C.</p>
Polishing: see section 7		
	<p>Insert all the Termini "C" into the Insulator "B".</p> <p>When you insert the Terminus "C", be careful to turn it during the insertion to not "bend" the contact O-ring.</p>	
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;">Receptacle</div> 	<p>Pin Layout front view.</p>	
	<p>Place the Support Washer "D" around the Termini "C".</p>	
	<p>Push the contact bloc (Termini "C" + Insulator "B") with the Support Washer "D".</p>	
	<p>Insert the Wire Set Body "H" into the Connector Body "A".</p>	

Picture	Process	Tools
 <p>The top image is a cross-sectional diagram of a cable connector assembly. It shows a grey connector body with a black wire set nut being tightened onto a cable with red and yellow conductors. The bottom image is a photograph showing a torque wrench being used to tighten a component on a metal assembly tray.</p>	<p>Screw the Wire Set Nut "I" on the Connector Body "A".</p> <p>Recommended torque : 5.0 Nm</p>	<p>Torque wrench [5Nm] Size 16</p>







6 Terminus assembly




Assembly steps



Components list :

- A – Housing O-Ring
- B – Termini Housing
- C – Ferrule O-Ring
- D – Ferrule
- E – Spring
- F – Termini Closure



Picture	Process	Tools
	Slide over the cable : <ul style="list-style-type: none"> - the Termini Closure "F" - the Spring "E" 	
Prepare the cable according to stripping dimension from the relevant section.		
	Insert epoxy into the Ferrule "D" until a little drop appears at the Ferrule end. Carefully insert the fiber into the back of the Ferrule "D". Make sure the buffer slides inside the Ferrule and abuts the ceramic.	Extended Working Life, 2-Part Epoxy, 2.5 Gram Packet Frs : FIBER OPTIC CENTER Ref : ET383ND-2.5G
 <p>Excess epoxy can affect mechanical function</p>	Remove any excess epoxy from the assembly.	
	Cure the epoxy.	120 +10/- 20[°C] during 20 min.
	Cleave fiber.	Scribe Tool




	<p>Position the Ferrule O-Ring "C" on the Ferrule "D" as shown on the top left picture.</p> <p>Slide the Spring "E" and Termini Closure "F" at the back of the Ferrule "D" and assemble them into the Termini Housing "B".</p>	
	<p>Position the Housing O-Ring "A" on the Termini Housing "B" as shown on the left picture.</p>	
Solder contact		
	<p>Solder the wire to the contact.</p>	



7 Polishing

It is recommended polishing the fiber using a polishing machine.

Polish the fiber according to the machine manufacturer's instructions.


Picture	Process	Tools
PC termini		
	<p>Step1 : Air polish</p> <p>Holding the polishing bushing and terminus, place the polishing bushing on the film. Using light pressure on the ferrule, polish the endface of the ferrule in a small circular motion.</p>	<ul style="list-style-type: none"> ▪ Polishing film: 9µm Silicon carbide ▪ Polishing Pad : N/A ▪ Lubricant: N/A ▪ Tool: FO-10090
	<p>Clean the polishing pad with demineralized water and lint-free cloth, from the center outwards.</p> <p>Spray some demineralized water on the polishing pad and place the polishing film, starting at edges of the polishing pad.</p> <p>Spray abundantly demineralized water on the polishing film.</p>	

	<p>Step 2 :</p> <p>Polish the termini with 5 µm Silicon carbide polishing film, until no peripheral chips are visible.</p> <p>Do not remove more than 100 µm.</p>	<ul style="list-style-type: none"> ▪ Polishing film: 5µm Silicon carbide ▪ Polishing Pad : 90 duro black ▪ Lubricant: DI-water ▪ Fixture tool: FO-10019
	<p>Wipe abundantly the polishing tool holding the termini with demineralized water and clean it carefully with a lint-free cloth.</p> <p>Use an air pressure gun to remove residual water.</p>	
	<p>Clean the polishing pad with demineralized water and lint-free cloth, from the center outwards.</p> <p>Spray some demineralized water on the polishing pad and place the polishing film, starting at edges of the polishing pad.</p> <p>Spray abundantly demineralized water on the polishing film.</p>	
	<p>Step 3 :</p> <p>Polish the termini with 1 µm Diamond polishing film in an 8 pattern motion (or pattern of the polishing machine).</p>	<ul style="list-style-type: none"> ▪ Polishing film: 1 µm Diamond ▪ Polishing Pad: 80 duro green ▪ Lubricant: DI-water ▪ Fixture tool: FO-10019



Wipe abundantly the polishing tool holding the termini with demineralized water and clean it carefully with a lint-free cloth.

Use an air pressure gun to remove residual water.



Clean the polishing pad with demineralized water and lint-free cloth, from the center outwards.

Spray some demineralized water on the polishing pad and place the polishing film, starting at edges of the polishing pad.


Spray abundantly demineralized water on the polishing film.

Step 4 :

Polish the termini with AngstromLap Final Polish SiO₂ in an 8 pattern motion.

Do not clean the polishing tool after this step, to avoid creating scratches on the polished ferrule.

- Polishing film: AngstromLap Final Polish SiO₂
- Polishing Pad: 80 duro green
- Lubricant: DI-water
- Fixture tool: FO-10019




Geometrical control :

Ferrule Radius [mm]:
Min 5 - Max 12

Apex Offset [μ m]:
Min 0.0 – Max 50.0

If fail, repeat from step 3.



Fiber core inspection :


Examine the endface of the ferrule for scratches according to left pictures.

If fail, repeat from step 4.



If not installing the connector immediately, install a protective cover onto terminus to prevent contamination to the endface of the ferrule.

8° APC termini















Step1 : Air polish



Holding the polishing bushing and terminus, place the polishing bushing on the film.

Using light pressure on the ferrule, polish the endface of the ferrule in a small circular motion.

- Polishing film: 9 μ m Silicon carbide
- Polishing Pad : N/A
- Lubricant: N/A
- Tool: FO-10090



    	<p>Clean the polishing pad with demineralized water and lint-free cloth, from the center outwards.</p> <p>Spray some demineralized water on the polishing pad and place the polishing film, starting at edges of the polishing pad.</p> <p>Spray abundantly demineralized water on the polishing film.</p>	
   	<p>Step 2 :</p> <p>Polish the termini with 8° angle using the fixture tool.</p> <p>Make sure the endface of the ferrule is fully polished, as shown on the left pictures.</p> <p>If not, repeat from step 2.</p>	<ul style="list-style-type: none"> ▪ Polishing film: 5µm Diamond ▪ Polishing Pad: Glass ▪ Lubricant: DI-water ▪ Fixture tool: TX00.285
 	<p>Wipe abundantly the polishing tool holding the termini with demineralized water and clean it carefully with a lint-free cloth.</p> <p>Use an air pressure gun to remove residual water.</p>	



Clean the polishing pad with demineralized water and lint-free cloth, from the center outwards.



Spray some demineralized water on the polishing pad and place the polishing film, starting at edges of the polishing pad.

Spray abundantly demineralized water on the polishing film.

Step 3 :


Polish the termini with 1 μm Diamond polishing film in an 8 pattern motion (or pattern of the polishing machine).

- Polishing film: 1 μm Diamond
- Polishing Pad: 80 duro green
- Lubricant: DI-water
- Fixture tool: TX00.285



Wipe abundantly the polishing tool holding the termini with demineralized water and clean it carefully with a lint-free cloth.

Use an air pressure gun to remove residual water.



Clean the polishing pad with demineralized water and lint-free cloth, from the center outwards.

Spray some demineralized water on the polishing pad and place the polishing film, starting at edges of the polishing pad.

Spray abundantly demineralized water on the polishing film.

Step 4 :

Polish the termini with AngstromLap Final Polish SiO₂ in an 8 pattern motion.

Do not clean the polishing tool after this step, to avoid creating scratches on the polished ferrule.



- Polishing film: AngstromLap Final Polish
- Polishing Pad:80 duro green
- Lubricant: DI-water
- Fixture tool: TX00.285

Geometrical control :

Ferrule Radius [mm]:
Min 5 - Max 12

Apex Offset [µm]:
Min 0.0 – Max 50.0

If fail, repeat from step 3.



Fiber core inspection :

Examine the endface of the ferrule for scratches according to left pictures.



If fail, repeat from step 4.



If not installing the connector immediately, install a protective cover onto terminus to prevent contamination to the endface of the ferrule.

8 Appendix

Tool drawing for crimping the sleeve to the contact



Tool drawing for crimping the ground contact to the rear body (FOH)

